



Existing Conditions



Future Conditions

Note: This alignment is located in a designated utility corridor.

Summary of Visual Changes

**Type/Sensitivity of Users:** Local and long distance travelers with a moderate interest in the visual quality of the area  
**Volume of Users:** High  
**T/L Distance from Viewer:** Middleground to foreground crossing views  
**T/L Prominence in Landscape:** Moderate to high - partially backdropped but some towers prominently skylined on nearby ridges  
**Existing Modifications:** Existing wood pole transmission line

**Contrast Rating:** Strong  
**VRM Class:** III (Interim)  
**Visual Impact Rating:** Medium

KOP 27  
Hwy 50 Robinson Summit

Figure 3.9-28